



A
PURAVANKARA HOME AT
SPARKLING SPRINGS

Pride of owning something precious

SPARKLING SPRINGS

AT THE PURVA SOUND OF WATER

Construction Updates

March 2024

Dear Esteemed Customer,


Greetings from Puravankara

It gives us immense pleasure to update you through this edition of Puravankara Newsletter and provide you with the latest information about your home in Sparkling Springs. As we move ahead, we at Puravankara sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

We are grateful for your kind cooperation.

Team Sparkling Springs





Sparkling Springs

Off Bannerghatta Main Rd, Bengaluru



Construction Updates

Overall view

PHASE 2



- Villa 3 - Structure completed, block work in progress.



- Villa 4 - PCC work completed.

Actual site photograph



- Villa 5 - Plinth beam work is completed, grade slab work in progress.



- Villa 6 - Column up to 1st floor completed.
- Villa 7 - Column up to 1st floor completed.
- Villa 8 - Grade slab work in progress.

Actual site photograph



- Villa 9 – Column above first floor slab in progress.



- Villa 10 - Column up to 1st floor completed.
- Villa 11 - First floor slab work completed.

Actual site photograph



- Villa 13 - Column up to 1st floor completed.
- Villa 12 - Column up to 1st floor completed.



- Villa 14 - 1st floor slab work completed.

Actual site photograph



- Villa 16 - Structure, block work is completed. Plastering work in progress.
- Villa 17 - Column above first floor slab is completed. Roof slab work has commenced.



- Villa 18 - Column above first floor slab completed.
- Villa 19 - Structure work, block work & plastering is completed. Flooring work in progress.
- Villa 20 - Column above first floor slab completed.
- Villa 21 and 22 - Structure work, block work completed & plastering work in progress.

Actual site photograph



- Villa 23 – First floor slab in progress.
- Villa 24 - Plinth beam is completed. Grade slab work in progress.



- Villa 25 - Column work above 1st floor is completed, roof slab work in progress.
- Villa 26 - Roof slab work in progress.

Actual site photograph



- Villa 28 - Roof slab work in progress.



- Villa 29 - First floor slab completed.
- Villa 30 - First floor slab completed.

Actual site photograph



- Villa 31 - Roof slab work completed.



- Villa 32 - Roof slab work completed.

Actual site photograph



- Villa 33 – First floor slab work in progress.
- Villa 34 – Plinth beam work completed, grade slab work in progress.
- Villa 35 - First floor slab completed.



- Villa 62 - Structure work completed, block work in progress.
- Villa 63 - Structure work completed, block work in progress.
- Villa 64 - Roof slab work in progress.
- Villa 65 - Roof slab completed, staircase head room work & block work in progress.

Actual site photograph



- Villa 66 - Roof slab completed.
- Villa 67 - External plastering completed, flooring work in progress.
- Villa 68 - First floor slab completed.



- Villa 69 - First floor slab work completed.
- Villa 70 - Grade slab work completed.
- Villa 71 – Roof slab completed.

Actual site photograph



- Villa 72 - Grade slab completed.
- Villa 73 - Roof slab work completed.
- Villa 74 - column above 1st floor slab completed.
- Villa 75 - Roof slab work in progress.



- Overall

Actual site photograph

PHASE 3



- Villa 148 - Structure work completed, block work in progress.
- Villa 149 - Column up to 1st floor completed.



- Villa 151 - Roof slab work completed.
- Villa 152 - Roof slab work in progress.

Actual site photograph



- Villa 153 - First floor slab completed.
- Villa 154 - Column work above first floor slab in progress.
- Villa 155 - Roof slab work in progress.



- Villa 150 - Plinth beam work completed.
- Villa 156 - Plinth beam work completed.

Actual site photograph



- Villa 158 - Roof slab work in progress, block work in progress.
- Villa 157 - Column up to 1st floor completed.



- Villa 159 - Column above 1st floor completed.
- Villa 160 - Column up to 1st floor completed.
- Villa 161 - Column up to 1st floor completed.
- Villa 162 - Plinth beam work completed.

Actual site photograph



- Villa 165 - Column up to 1st floor completed.
- Villa 164 - Column up to 1st floor completed.
- Villa 163 - Column up to 1st floor completed.



- Villa 166 - 1st floor slab work in progress.

Actual site photograph



- Villa 167 - Plinth beam completed.
- Villa 168 - Plinth beam in progress.
- Villa 169 - Plinth beam is completed; column work up to 1st floor in progress.



- Villa 174 - Column up to 1st floor completed.
- Villa 173 - Column up to 1st floor completed.
- Villa 172 - Column up to 1st floor completed.
- Villa 171 - Column up to 1st floor completed, grade slab in progress.
- Villa 170 - Column up to 1st floor completed, grade slab in progress.

Actual site photograph



- Villa 175 - 1st floor slab in progress.
- Villa 176 - Column up to 1st floor completed.
- Villa 177 - Column up to 1st floor completed.



- Villa 178 - Column up to 1st floor in progress.
- Villa 179 - Column up to 1st floor completed.

Actual site photograph



- Villa 180 - 1st floor slab completed.
- Villa 181 - Column up to 1st floor completed.
- Villa 182 - Column up to 1st floor completed.



- Villa 185 - Roof slab work in progress.
- Villa 184 - Column up to 1st floor completed.
- Villa 183 - Column up to 1st floor completed.

Actual site photograph



- Villa 186 - Grade slab and column up to 1st floor completed.
- Villa 187 - Grade slab and column up to 1st floor completed.



- Villa 188 - Grade slab and column up to 1st floor completed.
- Villa 189 - Grade slab and column up to 1st floor completed.

Actual site photograph



- Villa 190 - Column up to 1st floor completed.
- Villa 191 - Column up to 1st floor completed.



- Villa 192 - Column up to 1st floor completed.
- Villa 193 - Column up to 1st floor completed.
- Villa 194 - Column up to 1st floor completed.
- Villa 195 - Column up to 1st floor completed.

Actual site photograph




- Villa 196 - Roof slab work completed, block work in progress.
- Villa 197 - Roof slab work in progress, block work in progress.



- Villa 198 - Roof slab work & block work in progress.
- Villa 199 - Column work above First floor slab completed.

Actual site photograph



- Villa 200 - Column up to 1st floor completed.
- Villa 201 - Column above 1st floor slab in progress.



- Villa 202 - Column up to 1st floor completed.
- Villa 203 - Column up to 1st floor completed.

Actual site photograph



- Villa 204 - Column up to 1st floor completed.
- Villa 205 - Column up to 1st floor completed.



- Villa 206 - Column above 1st floor slab completed.
- Villa 207 - 1st floor slab completed.

Actual site photograph

Contact us

Site Office :

Sparkling Springs

South Taluk, Kammanahalli Village , Begur Hobli Road,
Off Bannerghatta Main Rd, Bengaluru, Karnataka – 560076

Regional Office :

Puravankara Limited. #130/1, Ulsoor Road,
Bengaluru - 560 042

Email : crm@puravankara.com (Subject line – Project name/ unit number)

Call Us : +91 - 80-67724001 / 1 860 208 0000

Web : www.puravankara.com

OC Number :

JDBL (S)/ADBL/OC/11/2020-21