

PURAVANKARA



A
PURAVANKARA HOME AT
PURVA PROMENADE

Pride of owning something precious

PURVA PROMENADE

A PART OF PURVA PALM BEACH

Construction Updates

January 2024


Dear Esteemed Customer,

Greetings from Puravankara

It gives us immense pleasure to update you through this edition of Puravankara Newsletter and provide you with the latest information about your home in Purva Promenade. As we move ahead, we at Puravankara sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

*We are grateful for your kind cooperation.
Team Purva Promenade*





Purva Promenade

Hennur Road, Hanumanthappa Layout,
Kyalasanahalli, Bengaluru



Construction Updates

Overall view

Tower R



Actual site photograph



PROGRESS TIMELINE



October 23 November 23 December 23 **January 24**

TOWER STATUS

- Ground floor to 9th floor tiling work completed.
- Ground floor to 9th floor door installation work completed.
- Ground floor to 9th floor window installation completed.
- Ground floor to 9th floor CP & sanitary fixing work completed.
- Ground floor to 9th floor electrical work completed.
- Ground floor to 9th internal final coat paint completed.
- Service & passenger lift installation and commissioning work completed.
- Fire, staircase, flooring work completed.
- Final coat painting work completed.
- Terrace water proofing work completed.
- External final coat painting completed.



MILESTONES ACHIEVED

- Ground floor to terrace staircase final coat painting completed.
- 1st floor 1 flat final coat painting completed.
- 1st Floor 1 flat CP & sanitary fixing work completed.

Tower S



Actual site photograph



PROGRESS TIMELINE



October 23 November 23 December 23 **January 24**

TOWER STATUS

- Ground floor to 9th floor tiling work completed.
- Ground floor to 9th floor door installation work completed.
- Ground floor to 9th floor window installation completed.
- Ground floor to 9th floor CP & sanitary fixing work completed.
- Ground floor to 9th floor electrical work completed.
- Ground floor to 9th internal final coat painting completed.
- Service & passenger lift installation and commissioning work completed.
- Flooring work completed.
- Fire staircase final coat painting competed.
- Terrace water proofing work completed.
- External final coat painting completed.



MILESTONES ACHIEVED

- 1st floor 2 flats internal final coat painting completed.
- Ground floor to terrace staircase final coat painting completed.

Tower T



Actual site photograph



TOWER STATUS


- Ground floor to 9th floor tiling work completed.
- Ground floor to 9th floor door installation work completed.
- Ground floor to 9th floor window installation completed.
- Ground floor to 9th floor CP & sanitary fixing work completed.
- Ground floor to 9th Floor electrical work completed.
- Ground floor to 9th internal final coat painting completed.
- Service & passenger lift installation and commissioning work completed.
- Flooring work completed.



MILESTONES ACHIEVED

- Staircase final coat painting completed.
- Fire staircase final coat painting work completed.
- Terrace water proofing work completed.
- External final coat painting completed.

PROGRESS TIMELINE



October 23

November 23

December 23

January 24

Tower U



Actual site photograph



PROGRESS TIMELINE



October 23 November 23 December 23 **January 24**

TOWER STATUS

- Ground floor to 9th main flooring works completed.
- Ground floor to 9th floor door & window fixing completed.
- Terrace waterproof work completed.
- External final coat painting work completed.
- Service & passenger lift installation and cladding work completed.
- Service lift commissioning work completed.
- All floor lift Lobby flooring works completed.
- Staircase fire door completed.
- Flat internal wiring ground floor to 9th floor completed.
- Terrace level firefighting work completed.
- Fire staircase flooring work completed.
- 2nd to 8th CP & sanitary fixing work completed.



MILESTONES ACHIEVED

- 3rd to 7th floor flats internal final coat painting completed.
- Fire staircase 1st coat painting work completed.
- 2nd to 8th floor flat internal 1st coat painting completed.
- 3rd to 7th flats internal final coat painting completed.



UPCOMING MILESTONES

- Completion of ground floor, 1st, 2nd, 8th and 9th floor flats internal final coat painting work.
- Completion of ground floor, 1st & 9th floor sanitary work.

Other Activities

Driveway



Basement



EXTERNAL WORKS

- Driveway
- Basement

Actual site photograph

PROGRESS TIMELINE



Other Activities

Podium Landscape



Actual site photograph


Podium Landscape



EXTERNAL WORKS

- Podium Landscape

PROGRESS TIMELINE



October 23

November 23

December 23

January 24

Contact us

Site Office :

Purva Promenade

Hennur Road, Hanumanthappa Layout, Kyalasanahalli,
Bengaluru, Karnataka – 560077.

Regional Office :

Puravankara Limited. #130/1, Ulsoor Road,
Bengaluru - 560 042

Email : crm@puravankara.com (Subject line – Project name/ unit number)

Call Us : +91 - 80-67724001 / 1 860 208 0000

Web : www.puravankara.com

RERA Registration Number :

PRM/KA/RERA/1251/446/PR/200205/003243